# PRODUCT LINES 2020

瑞声科技 AAC TECHNOLOGIES
www.aactechnologies.com

- MEMS

ALANGO
www.alango.com

- AGC

ANALOG DEVICES 超越一切可能™
www.analog.com

- ADC
- DAC
- MEMS
- DSP

ADI Power by Linear™

- DC/DC
- isoPower
- LDO
- LED IC
- IC
- µModule

antenova m2m
www.antenova-m2m.com

- M2M, 2G/3G/LTE Lora wifi Zigbee , GPS

apm communication
www.apmcomm.com

- WIFI
- +WIFI / +WIFI

axetris Company of the Leister Group
www.axetris.com/zh-cn

- , 2 to 14 µm

ATP
www.atpinc.com

- SD
- microSD
- SecurStor-enabled SD & microSD cards
- Compact Flash (CF)
- CFast
- SSD
  - M.2 NVMe
  - M.2 SATA
  - 2.5" SSD
  - SecurStor-enabled SSDs
  - mSATA
  - eUSB
  - U
- NAND
  - e.MMC
  - SecurStor-enabled managed NAND solutions
- DRAM
  - DDR4
  - DDR3 8Gbit component based modules
  - DDR3
  - DDR2
  - DDR1
  - SDRAM

百瑞互联 BARROT
www.barrot.com.cn

- IoT , , , , , ,
- Audio , TWS , , Speaker Phone,
- / AVN, DA, Car Audio, HUD, OBD, TBox
- Bluetooth Stack IP

BOURNS®
www.bourns.com

- TBU®
- /PTC -
- -

CRANE AEROSPACE & ELECTRONICS
Interpoint® Products
www.interpoint.com

- dc-dc EMI

ECS INC INTERNATIONAL
www.ecsxtal.com

复旦微电子
www.fmsh.com

- EEPROM 1 Kbit-1024 Kbit
- SPI NOR Flash 512 Kbit-32 Mbit
- SPI NAND Flash 1 Gbit-4 Gbit
- NFC+IIC/SPI NVM - NFC

GOOD-ARK SEMICONDUCTOR
www.goodarksemi.com

- MOS
  - VDS=8V thru 900V
  - ID=100mA thru 220A
  - N N/P+P MOS
  - N+P MOS
- TVS
  - & ESD TVS
  - TVS
- MEMS
  - SCRs
  - Triacs
- /

ittim
I think therefore I am.
www.ittim.cn

- Wi-Fi IoE, Wi-Fi AP

MICROCHIP
www.microchip.com

- PIC® 8/16/32
- EEPROM, SRAM
- SPI/UART WIFI
- CAN, LIN, USB SPI
- [SST] NOR
- [Supertex] LED , ,
- [SMSC] USB/Ethernet
- [Micrel] DC/DC ,
- MEMS
- [Atmel] AVR 8 /32 MCU SMART ARM ;

Microsemi
a Microchip company
www.microsemi.com

- &
- &
- &
- , PCIe
- PoE
- , &
- &

Novaiot
www.iotnova.com

- , 4K Wi-Fi IoT, Wi-Fi Client, Wi-Fi AP

OMRON
www.ecb.omron.com.cn

- / / / /
- MOSFET
- MIL
- DIN

OTAX
www.otax.com.cn

- / /
- PCMCIA
- CPU

PM SPECIAL MEASURING SYSTEMS
a Phoenix Mecano company
www.pm-sms.com

PYREOS
SENSOR INNOVATION
www.pyreos.com

qorvo
all around you
www.qorvo.com

- GSM/GPRS/EDGE/CDMA/WCDMA/TD-SCDMA/4G LTE
- 5G , FEM
  5G RF RFFE
- PA TRx / / ASM LTE
- RF Wi-Fi
- 2.4G MHz Wi-Fi 5G MHz Wi-Fi
  Wi-Fi
- /
- / DC-DC
- [Decawave] ,
  (UWB) , ,

**Qualcomm**
www.qualcomm.cn

- , TWS
- , GPS GLONASS Beidou Galileo
- Wi-Fi

**ScioSense**
www.sciosense.com

- , VOC

**SENSITRON SEMICONDUCTOR**
Your Power Solutions Provider
www.sensitron.com

- / / /
- SPM
- IGBT/MOSFET
- / /

**Silicon Mobility**
www.silicon-mobility.com

- OLEA® FPCU , 100
- OLEA®COMPOSER ,
- OLEA®APP , OLEA®

**SIMCom**
a SUNSEA AIOT company
www.simcom.com

- GSM/GPRS
- GSM/GPRS + GNSS
- WCDMA/HSxPA/HSPA+
- CDMA 1xRTT/EV-DO
- LTE
- GNSS GPS/Glonass/BD
- GSM/GPRS, WCDMA/HSPA+, LTE

**TDK TDK-Micronas GmbH**
www.micronas.com

- TMR Angle Sensors

**TRINAMIC**
MOTION CONTROL
Now part of Maxim Integrated
www.trinamic.com

**Thundercomm**
www.thundercomm.com/app_en/index

- Thundercomm TurboX™ SOM , Qualcomm® ™ , , VR/AR, …

**华润华晶微电子**
WUXI CHINA RESOURCES HUAJING MICRO
www.crhj.com.cn

- MOS
- , , IGBT

# LED

**SEOUL SEMICONDUCTOR**
www.seoulsemicon.com

LED
- High Power 4040/5050/3535
- Mid Power 5630/3030/3528
- Wicop
- COB
- Sunlike
- Filament
- Modules Acrich Module/DC Module
- Drivers Nano Driver/Micro Driver

**SEOULVIOSYS**
www.seoulviosys.com

UV LED
- UVA - 340, 365, 375, 385, 395, 405nm
- UVB - 310nm
- UVC - 275nm

k(?q(@- 289% 0(É13108-3
3108, 31/F, Skyline Tower, 39 Wang Kwong Road,
Kowloon Bay, Hong Kong

| | | | |
|---|---|---|---|
| FJU | +852 2503 2212 | fIIU | +852 2503 1558 |
| FbU | info@excelpoint.com.hk | PÇU | www.excelpoint.com.cn |

## [illegible]*

7/ÿ§H5678&P-(gÔ1.RB0620;

| | |
|---|---|
| bPV | 200333 |
| FJU | +86 21 2220 3188 |
| fIIU | +86 21 2220 3199 |

[illegible]

$8gg[illegible]0823-3

| | |
|---|---|
| bPV | 100020 |
| FJU | +86 10 6580 2113 |
| fIIU | +86 10 6580 2117 |

[illegible]

g(/.Bp[illegible]1.RB06281:3

| | |
|---|---|
| bPV | 410013 |
| FJU | +86 731 8892 5495 |
| fIIU | +86 731 8892 5495 |

[illegible]

3b/[illegible]0(É7L-3

| | |
|---|---|
| bPV | 610017 |
| FJU | +86 28 8652 7611 |
| fIIU | +86 28 8662 8872 |

[illegible] /m$*

K /m/[illegible]1.RD3063114-3

| | |
|---|---|
| bPV | 350004 |
| FJU | +86 591 8335 7003 |
| fIIU | +86 591 8335 7003 |

[illegible]

0/m/[illegible]3203B-3

| | |
|---|---|
| bPV | 510620 |
| FJU | +86 20 3893 9561 |
| fIIU | +86 20 3809 4282 |

[illegible]

8/m/ [illegible]1.R5/[illegible]19-3

| | |
|---|---|
| bPV | 310002 |
| FJU | +86 571 8528 2185 |
| fIIU | +86 571 8690 6185 |

[illegible]

[illegible]77[illegible]0(É262:3

| | |
|---|---|
| bPV | 250101 |
| FJU | +86 531 8096 5769 |
| fIIU | +86 531 8096 5769 |

[illegible]

[illegible]90(É9-Ñ2-3

| | |
|---|---|
| bPV | 210005 |
| FJU | +86 25 8689 3130 |
| fIIU | +86 25 8689 3129 |

[illegible]

-q/b/m[illegible]1906-3

| | |
|---|---|
| bPV | 315100 |
| FJU | +86 574 8386 5759 |
| fIIU | +86 574 8386 5760 |

[illegible]

h/[illegible]003-3

| | |
|---|---|
| bPV | 266061 |
| FJU | +86 532 8502 6539 |
| fIIU | +86 532 8502 6543 |

[illegible]

[illegible]99%(7.R[illegible]-Ñ

| | |
|---|---|
| bPV | 518057 |
| FJU | +86 755 8364 0166 |
| fIIU | +86 755 2598 2255 |

[illegible]m$*

T/m/+T[illegible]1.R2619-3

| | |
|---|---|
| bPV | 215008 |
| FJU | +86 512 6530 8103 |
| fIIU | +86 512 6530 7929 |

[illegible]

[illegible]

A062601-3

| | |
|---|---|
| bPV | 430074 |
| FJU | +86 27 8769 0883 |
| fIIU | +86 27 8769 0663 |

[illegible]

5/gw/17[illegible]506-508%0(É9702-3

| | |
|---|---|
| bPV | 361008 |
| FJU | +86 592 5042 386/5163 916 |
| fIIU | +86 592 5042 385 |

[illegible]

[/[illegible]1.RB06701-3

| | |
|---|---|
| bPV | 710068 |
| FJU | +86 29 8765 1058 |
| fIIU | +86 29 8765 1059 |

## [illegible]k*

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| c0 | FJU | +86 136 2830 7074 | [illegible]4 | FJU | +86 138 5656 7447 | [illegible] | FJU | +86 139 2065 6573 | b/m | FJU | +86 138 0384 6359 |
| [illegible]m | FJU | +86 156 4083 6155 | 2o/m | FJU | +86 136 8076 4680 | 7of° | FJU | +86 150 6185 1831 | Eo? | FJU | +86 137 2622 4480 |
| [illegible]- | FJU | +86 158 8963 8656 | [illegible] | FJU | +86 156 0405 4122 | Bn% | FJU | +86 155 5222 0532 | | | |